



FIG.2










Ser. No. 10/521,471










FIG.6






FIG.7



LUMINOSITY MEASUREMENT RESULTS

(h c d)

	VEHICLE A (AIR CONDITIONER IS OFF)	VEHICLE A (AIR CONDITIONER IS ON)	VEHICLE B (AIR CONDITIONER IS OFF)
BEFORE GROUND MOUNTING	59800	53400	52600
AFTER GROUND MOUNTING	61800	59000	53900

FIG.8A





FIG.8B


Ser. No. 10/521,471


O 1 P E


MAR 0 8 2006

































FIG.15










FIG.17






FIG.18

Ser. No. 10/521,471






FIG.19






FIG.20






FIG.21




FIG.22



FIG.23